



Photo 1: View facing east of the excavated drainage ditch during excavation in April 2025. This location is approximately adjacent to 16 & 18 South Hunt Road.



Photo 2: View facing east of the excavated drainage ditch during excavation in April 2025. This location is approximately adjacent to the driveway access point to 14 South Hunt Road.



Photo 3: View facing east of the excavated drainage ditch following reestablishment of vegetation in July 2025. This location is approximately adjacent to 16 & 18 South Hunt Road (depicted during excavation in **Photo 1**).



Photo 4: View facing west of the excavated drainage ditch following reestablishment of vegetation in July 2025.



Photo 5: View facing west of the excavated drainage ditch following reestablishment of vegetation in July 2025.



Photo 6: View facing east of the excavated drainage ditch following reestablishment of vegetation in July 2025. This location is approximately adjacent to the driveway access point to 14 South Hunt Road (depicted during excavation in **Photo 2**).



Photo 7: View facing west of the excavated drainage ditch following reestablishment of vegetation in July 2025.